

# SODEREC INTERNATIONAL

<b>ACIDE FLUONITRIQUE</b>	<b>SODECOAT</b>	<b>FLUONITRIC ACID</b>
<b>Qualité technique</b>		<b>Technical grade</b>

<p style="text-align: center;">Formule chimique</p> <p>Aspect : limpide – incolore à légèrement jaune</p> <p style="text-align: center;">Odeur : irritante</p> <p style="text-align: center;">Masse volumique (environ)</p> <p style="text-align: center;"><b>Répartition massique</b></p> <p><b>Formulation</b> <b>a la demande</b></p> <p style="text-align: center;">Acide fluorhydrique (HF)</p> <p style="text-align: center;">Acide nitrique (HNO<sub>3</sub>)</p> <p style="text-align: center;">Eau</p> <p style="text-align: center;"><b>N° de tarif douanier</b> <b>CODE ONU</b></p> <p><b>Etiquetage : - Route : 8 et 6.1</b> <b>- Risques industriels : T+ et C</b></p> <p style="text-align: center;"><b>Conditionnement</b></p> <p style="text-align: center;">Fût en polyéthylène</p> <p style="text-align: center;">Fût métallique doublé PE</p> <p style="text-align: center;"><b>Conseils de stockage</b></p> <p>Les récipients seront étiquetés et maintenus fermés, conservés dans un endroit bien ventilé, frais et sec, à l'écart de tout danger d'inflammation et de matières susceptibles de réagir</p> <p>Après vidange les bouchons doivent être remis en place avec leurs joints et correctement serrés.</p> <p style="text-align: center;"><b>Protection individuelle</b></p> <p>Un vêtement anti-acide est indispensable, ainsi que le port de bottes, gants et lunettes. Effectuer les manipulations avec un masque ou sous forte ventilation . Le port d'un écran facial ou d'un appareil respiratoire peut être nécessaire suivant les conditions de travail.</p>	<p>HF – HNO<sub>3</sub></p> <p>1,23</p> <p>X %</p> <p>Y %</p> <p>Z %</p> <p>2811.1100</p> <p>2922</p> <p>30 l. ( 30 kg)</p> <p>205 l (200 kg)</p>	<p>Chemical formula</p> <p>Appearance : limpid – Colourless to yellowish</p> <p>Smell : irritating</p> <p>Specific gravity (about)</p> <p><b>Mass repartition</b></p> <p>Hydrofluoric acid (HF)</p> <p>Nitric acid (HNO<sub>3</sub>)</p> <p>Water</p> <p><b>Customs tariff N°</b> <b>UN CODE</b></p> <p><b>Labelling : - Road : 8 and 6.1</b> <b>- Industrial hazards: T+ and C</b></p> <p><b>Packaging</b></p> <p>Polyethylene drum</p> <p>Polylined steel drum</p> <p><b>Storage conditions</b></p> <p>The containers must be labelled, stored upright and kept tightly closed. The store should be cool, shaded and away from sources of heat and incompatible products. Good ventilation is essential</p> <p>All part used or empty packages should be tightly closed and returned to store after use.</p> <p><b>Personal protection</b></p> <p>Clothing and equipment giving body, eye, foot and hand protection should always be worn. Depending on working system, additional protection such as face visor or respiratory equipment may be necessary</p>
---	---	--

**Service commercial**

Chemin des Agriculteurs  
26700 PIERRELATTE (France)  
Tél. : +33 . (0) 4. 75.96.96.50 ou / or  
+33. (0) 4.75.96.96.52  
Fax : +33 (0) 4. 75.96.96.51

**Commercial department**

**Usine** Standard Tél. 04. 75.96.80.99 - Fax. 04. 75.98.42.50 **Plant**

Référence qualité Approuvée par	<b>SODECOAT - 4/99</b> PJ PLANEILLE	Quality reference Approved by
------------------------------------	--	----------------------------------